


EXPLODED VIEW



DELIVERING OF SPARE PARTS


Please note: When ordering spare parts please always mention:Model of the machine, Serial number and Reference number of the part  
**SHOULD REF. NUMBERS MISSING, NO SPARE PART WILL BE DELIVERED.**

LIST OF SPARE PARTS

Ref. No.	Description	Ref. No.	Description	Ref. No.	Description	Ref. No.	Description
01	Washer 華司	31	Pivot 支架軸	60	Vice lever 虎鉗柄	91	Fixed blade guide plate 培林座
02	Base 底座	32	Bearing cover 偏心套	61	Bearing 培林	92	Mobile blade guide plate 大培林座
03	Bar stop rod 長度桿	33	Washer 華司	62	Bearing cover 培林蓋	93	Bush 虎鉗套管
04	Cool pump 冷卻馬達	34	Key 8 x 7 x 25 mm鍵	63	Vice handwheel 手輪	94	(手切)Toger switch 微動開關
05	Bar stop 長度板	35	Reducer 齒輪箱	64	Spring 彈簧	95	Condenser(Motor) 電容器 (optional)
06	Countervice 虎鉗下座	36	Motor 馬達	65	Spring connection 拉鉤	96	Coolant distributor 水分頭
07	Valve 水開關	37	round table 圓座	67	Revolving arm 旋轉座	97	Stand 腳架
08	Vice jaw 前檔板	38	Plate(optional) 油壓護蓋	68	Rod 彈簧把柄	98	Nut M10 螺帽
09	Vice 虎鉗上座	39	Mobile blade guide plate 大培林座	69	Stop bolt 固定軸	99	Pivots centric 培林軸正心
10	Body frame 鋸弓	40	Switch(optional) 開關	70	Micro switch(optional) 微動	100	Brush 鋼刷組
11	Casing 底座蓋	41	hand wheel 調整栓	71	Block 固定板	101	PIN 培林座插削
12	Motor Fan 馬達扇葉	42	Threaded shaft 拉塊桿	72	Hex. nuts 螺帽	102	Bracket 支架
13	Motor Cover 馬達蓋	43	Spring washer 彈簧片	73	Rubber connection 冷卻螺絲	104	Pivots excetric 培林軸偏心
16	Arm 頂料板	44	Grip 調整栓柄	74	Arm 長支架	105	Blade Tension Gauge 壓力錶 (optional)
17	Filter 網	45	Pin 調整螺絲	75	Bolt 螺栓	106	Switch 微動開關
18	Bush 旋轉螺帽	46	Handwheel 調整栓	76	Blade guard 長保護片	107	Key 鑰匙
19	Pin 旋轉軸	47	Return flywheel & 上鋸輪	77	Handle 任意把手	108	block 微動固定板
20	Lever 旋轉柄(長把手)	48	Hex. Nut 螺帽	78	Bearing 6082Z 608培林		
21	Fixed blade guide plate 培林座	49	Bearings 2Z/6205 6205培林	79	Hand wheel 枝架栓頭		
22	Key 7x7x35mm 鍵	50	Saw blade 鋸片	80	Handle 開關手把		
23	Bearing 培林	51	C-ring C型扣	81	Water Pipe 水管		
24	Motor flywheel 下鋸輪	52	Hex, nuts. 螺帽	82	Rust Plate 擋屑板		
25	Washer 蓋	53	Blade sheel shaft 上鋸輪軸	83	L. Bladeguard 保護片		
26	Shaft 鋸輪主軸	54	Block blade tersion 滑座	84	Switch set 開關		
27	Blade cover 鋸弓護蓋	55	Handle 手柄	85	Brush (optional) 鋼絲輪組		
28	Ring nilons 培林蓋	56	Lever 手柄桿	86	Switch Shelf 開關架		
29	Bearing 32006 培林	57	Vice screw 角牙桿	87	Scale 表尺		
30	Ring nut M30 主軸帽	58	SCALE 指針	89	Cylinder(optional) 油壓缸		
		59	Vice spring 彈簧	90	Pin(optional) 油壓缸螺絲		

# ELECTRICAL CIRCUIT DIAGRAM CY-210/CY-210A

Rexom fuse 16A  
Power Supply  
3 PH / 50HZ / 400V  
LIMIT OF EQUIPMENT



## Electrical parts list

Part No	Name	Dscription	Producer	Mark
T01	MS1	MS	SHIHLIN	CE
T02	O.L	OVER RELAY	SHIHLIN	CE
T03	M1	SAW MOTOR	GEORGE	CE
T04	M2	PUMP MOTOR	GEORGE	CE
T05	COOL	COOL SWITCH	TEND	CE
T06	PT	POWER TRANSFORMER	GEORGE	CE
T07	F1	FUSE	DEMEX	CE
T08	SAFE MICRO 1	MICRO SWITCH	HAILY	CE
T09	EMS	EMERGENCY STOP	DEMEX	CE
T10	OFF	PUSH BUTTEN	TEND	CE
T11	ON	PUSH BUTTEN	TEND	CE
T12	SPEED	CAM SWITCH	GEORGE	CE
T13	SAFE MICRO2	MICRO SWITCH	HAILY	CE